

Work Order ID 63129

Thursday, October 21, 2010 1:26:07 PM



Page 1

Item ID: D350-607-511

Accept



Setup Start



Revision ID:

Stop



Item Name: Quick Release Basket Mounting Installation

Start Date: 10/21/2010 Start Qty: 1.00



Cust Item ID:

Required Date: 10/28/2010 Req'd Qty: 1.00



Customer:

Reference:

Approvals:

Process Plan:

R

Date:

10/10/21

Tooling:

Date:

Run Start



QC:

Date:

SPC (Y/N):

Date:

Stop



Sequence ID/
Work Center ID

Operation
Description

Set Up/
Run Hours

Tool ID

Tool #

Plan
Code

Accept
Qty

Reject
Qty

Reject
Number

Insp.
Stamp

Draw Nbr

Revision Nbr

D350-607-3

A

100

0.00



DOCUMENT CONTROL

DC

Memo

0.00

Document Control

Photocopy bluefile & type labels per PPPD350-607-511 CHG001

S 10/10/25

Hager BG 10-10-22

140

0.00



Pick Kit

Packaging

Memo

0.00

Packaging

10/10/25 SP 10

150

0.00



QC4- 100% Inspect kits for completeness

QC

Memo

0.00

Quality Control

S 10/10/25

(X1)

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Work Order ID 63129

Thursday, October 21, 2010 1:26:07 PM

Page 2

Item ID: D350-607-511

Accept

Setup Start

Revision ID:

Stop

Item Name: Quick Release Basket Mounting Installation

Start Date: 10/21/2010 Start Qty: 1.00

Cust Item ID:

Required Date: 10/28/2010 Req'd Qty: 1.00

Customer:




Reference:

Approvals: Process Plan: _____ Date: _____ Tooling: _____ Date: _____



Run Start

QC: _____ Date: _____ SPC (Y/N): _____ Date: _____

Stop

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
160  Packaging	Packaging	0.00							
Packaging	Memo	0.00							
Packaging	Identify and pack for shipping as per PPP D350-607-511 Location: 								
170  QC	QC21- Final Inspection - Work Order Release	0.00							
Quality Control	Memo	0.00							

REVA

10/10/25  1010/10/25 MF
10-10-25

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

Picklist Print

Thursday, October 21, 2010 1:26:12 PM

Page 2

Work Order ID: 63129

Parent Item: D350-607-511

Parent Item Name: Quick Release Basket Mounting Installation

Start Date: 10/21/2010

Required Date: 10/28/2010

Start Qty: 1.00

Required Qty: 1.00

AN4-14A

Purchased

No

140

Each

187.0000

16

16

Bolt

Location

Loc Qty

Loc Code

ST357

171

114752

1

115371

70

115936

100

ST358

16

113359

16

MS21042L4

Purchased

No

140

Each

3,253.000

16

16

Nut

Location

Loc Qty

Loc Code

ST300

3253

113422

68

114523

8

114718

16

114784

32

115108

129

115589

1900

115621

1100

NAS1149F0432P

Purchased

No

140

Each

214.0000

32

32

Washer

Location

Loc Qty

Loc Code

ST275

214

112940

92

114405

1

114576

10

114718

8

115698

103

Thursday, October 21, 2010 1:26:12 PM

Shop Packet Print

Page 2

W/O:		WORK ORDER CHANGES					
DATE	STEP	PROCEDURE CHANGE	By	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector

Part No: _____ PAR #: _____ Fault Category: _____ NCR: Yes No DQA: _____ Date: _____

Resolution: _____ Disposition: _____ QA: N/C Closed: _____ Date: _____

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification Section C	Approval Chief Eng	Approval QC Inspector
			Initial Chief Eng	Action Description Chief Eng	Sign & Date			

NOTE: Date & initial all entries

4.0 WEIGHT AND BALANCE

Installation	Weight	LATERAL		LONGITUDINAL	
		Arm	Moment	Arm	Moment
D350-607-541 (Standard Basket)	80.7 lb 36.6 kg	± 49.1 in ± 1.25 m	± 3962 in-lb ± 45.8 m-kG	135 in 3.43 m	10895 in-lb 125.5 m-kG
D350-607-543 (Lightweight Basket)	65.7 lb 29.8 kg	± 49.1 in ± 1.25 m	± 3226 in-lb ± 37.3 m-kG	135 in 3.43 m	8870 in-lb 102.2 m-kG
D350-607-545 (Standard Basket)	58.7 lb 26.2 kg	± 49.1 in ± 1.25m	± 2882 in-lb ± 32.8 m-kG	135 in 3.43 m	7925 in-lb 89.9 m-kG
D350-607-547 (Lightweight Basket)	47.7 lb 21.6 kg	± 49.1 in ± 1.25 m	± 2342 in-lb ± 27.0 m-kG	135 in 3.43 m	6440 in-lb 74.1 m-kG
D350-607-511 (Quick Release Basket Mounting Kit)	7.2 lb 3.3 kg	± 36.9 in ± 0.94 m	± 266 in-lb ± 3.1 m-kG	135 in 3.43 m	972 in-lb 11.3 m-kG

5.0 PARTS LIST

QTY -541	QTY -543	QTY -545	QTY -547	QTY -511	QTY -501	PART NUMBER	DESCRIPTION
X						D350-607-541	HELI-UTILITY-BASKET
	X					D350-607-543	HELI-UTILITY-BASKET
		X				D350-607-545	HELI-UTILITY-BASKET
			X			D350-607-547	HELI-UTILITY-BASKET
1	1	1	1	X		D350-607-511	QUICK RELEASE BASKET MOUNTING KIT
					X	D350-607-501	CONVERSION KIT
1	1	1	1		1	D2690-6	LANYARD
				4	4	D3910-3	X-TUBE LUG
1	1	1	1		1	D3912-041	EYEBOLT RECEIVER ASSY
				8	8	D3984-030	RUBBER EXTRUSION, X-TUBE
1						D4030-041	LONG BASKET ASSY
	1					D4030-043	LONG BASKET ASSY, LIGHTWEIGHT
		1				D4032-041	SHORT BASKET ASSY
			1			D4032-043	SHORT BASKET ASSY, LIGHTWEIGHT
1	1	1	1		1	D4085-3	PLACARD-INSTRUCTIONS
1					1	D4086-200	PLACARD, MAX LOAD
	1				1	D4086-215	PLACARD, MAX LOAD
		1			1	D4086-220	PLACARD, MAX LOAD
			1		1	D4086-232	PLACARD, MAX LOAD
				1	1	D4148-041	FWD X-TUBE LUG ASSY
				1	1	D4149-041	AFT X-TUBE LUG ASSY
1	1	1	1		1	D4150-041	ATTACHMENT ARM ASSY
1	1	1	1		1	D4151-041	BASKET FWD HARDPOINT ASSY (LOWER)
1	1	1	1		1	D4151-043	BASKET FWD HARDPOINT ASSY (UPPER)
6	6	6	6		6	AN4-13A	BOLT
				16	16	AN4-14A	BOLT
1	1	1	1		1	AN4C15	BOLT
1	1	1	1		1	AN310C4	CASTELLATED NUT
1	1	1	1		1	MS17984-C413	QUICK RELEASE PIN
6	6	6	6	16	22	MS21042L4	NUT (OR MS21042-4)
1	1	1	1		1	MS24665-151	COTTER PIN
2	2	2	2		2	NAS1515H4L	WASHER
12	12	12	12	32	44	NAS1149F0432P	WASHER
3	3	3	3		3	NAS1149C0463R	WASHER

• COPYRIGHT © 2010 BY DART AEROSPACE LTD. •
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.

Revision: A
Date: 10.06.28